

May 6, 2025

To Whom It May Concern:

Re: Out of Specification Procedure

The Church & Dwight manufacturing facilities at Old Fort, Ohio and Green River, Wyoming have in place procedures for the identification, investigation, and reporting of deviations and Out-of-Specification (OOS) results that occur during the manufacture and testing of their regulated products. In addition, the investigation is extended to other lots that may have been associated with the failure as appropriate. Corrective and preventive actions are implemented as appropriate and tracked to completion.

Feel free to contact me with any questions.

Regards,

Muchaele madeno

Michelle Maddox Manager, Technical Service 609-806-1574 <u>michelle.maddox@churchdwight.com</u>

ARM & HAMMER[™] Performance Products